






*Technical Service
Information Bulletin
June 24, 2021*

**Subject:
Phasing crossbar out of Falcon
All Terrain, Falcon 2, Blackhawk
2 All Terrain and Sterling All
Terrain tow bars**



TSIB number 154



Over the next several months, Roadmaster will phase out the quick disconnect crossbar for the Falcon All Terrain, Falcon 2, Blackhawk 2 All Terrain and Sterling All Terrain tow bars. Most customers prefer our direct connect baseplates which do not need or use the quick disconnect crossbar. However, some baseplates may require the use of a crossbar. See below.



If your baseplate looks like either **A** or **B**, you don't need to acquire a crossbar.



If your baseplate looks like **C** or **D**, it will require a crossbar part number **910021-00** (sold separately) to connect the tow bar.